## Register of Listed Buildings at Risk (2013)

Listed Buildings At Risk	
Grade I	
Building/Address	Brunswick Square, 53
Priority	C (C)
Designation	Grade 1, Conservation Area
Condition	Poor, partially occupied
Ownership	Private
Summary	Terraced house 1825-27 in multiple occupancy. Rear elevation and outbuildings are in poor condition and parts of the building are not habitable. An Urgent Works Notice was served in 2013 to secure the carrying out of works to make the rear of the building weathertight. These works have largely been satisfactorily completed. The property has been marketed and discussions about its long term reuse and restoration are ongoing with the owner and potential purchasers.
Building/Address	Kings Road, The West Pier
Priority	A (A)
Designation	Grade 1, Conservation Area
Condition	Very bad
Ownership	Trust
Summary	Pier, 1864-66 by Eugenius Birch. Closed in 1975.Offered c£14 million grant by the Heritage Lottery Fund in March 1998. Stage II grant refused February 2004. English Heritage has declared its view that the combination of subsequent damage and cost of repair make restoration uneconomic from public funds.
	Grade II*
Puilding/Address	Marine Drive, Saltdean Lido
Building/Address Priority	C (C)
Designation	Grade II*
Condition	Poor, partially occupied
Ownership	Local Authority
Summary	Lido of 1938 by RWH Jones in Moderne style. Suffering from a maintenance backlog and in particular deterioration of its reinforced concrete. The long-term head lease was surrendered to the council in June 2012. The council invited bids for a new lease in 2013 and following that process the local Community Interest Company has been appointed as the preferred bidder for the building on a 60 year lease. Its repair and restoration will be subject to a bid to the Heritage Lottery Fund.
Building/Address	Middle Street 52-58 Hippodrome
Building/Address Priority	Middle Street, 52-58, Hippodrome C (C)
	Grade II*, Conservation Area
Designation	Glaue II , Conservation Alea

Condition	Poor, vacant
Ownership	Company
Summary	1897. Originally an ice rink, enlarged & converted to circus and
	theatre in 1901, architect Thomas Matcham. Further enlarged
	1939. New owner in place but no firm proposals for re-use at
	present. Some repair works carried out. Security presence on
	site. Extensive pre-application discussions have been carried
	out during 2013 on proposals to convert the building and
	adjoining land to a multi-screen cinema and supporting uses
	and a planning application is expected to be submitted shortly.
Desilation of Antalogue and	West Oferst Of Bayl's Obyest
Building/Address	West Street, St Paul's Church
Priority	A (A)
Designation	Grade II*
Condition	Poor, occupied
Ownership	Religious Organisation
Summary	Anglican church designed by Richard Cromwell Carpenter in
	1846-8 and built by George Cheeseman. The tower and spire
	by Richard Herbert Carpenter; the narthex, fishermen's institute
	(west end) and covered way by George Frederick Bodley.
	Large fragments of stone and flint have fallen from the tower,
	which is adjacent to a busy street. This has been temporarily
	protected. Tower suffers from apparent maintenance problems.
	English Heritage is leading discussions with the church.
	Crada II
B '' ' 'A ' '	Grade II
Building/Address	Adelaide Crescent , Retaining walls to south side of gardens,
Priority	Adelaide Crescent , Retaining walls to south side of gardens, C (C)
Priority Designation	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area
Priority Designation Condition	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor
Priority Designation Condition Ownership	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority
Priority Designation Condition	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus
Priority Designation Condition Ownership	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The
Priority Designation Condition Ownership	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork
Priority Designation Condition Ownership	Adelaide Crescent, Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are
Priority Designation Condition Ownership	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork
Priority Designation Condition Ownership Summary	Adelaide Crescent , Retaining walls to south side of gardens, C (C)  Grade II, Conservation Area  Poor  Local authority  Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.
Priority Designation Condition Ownership Summary Building/Address	Adelaide Crescent, Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church,
Priority Designation Condition Ownership Summary  Building/Address Priority	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church, C (C)
Priority Designation Condition Ownership Summary  Building/Address Priority Designation	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church, C (C) Grade II, Conservation Area
Priority Designation Condition Ownership Summary  Building/Address Priority Designation Condition	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church, C (C) Grade II, Conservation Area Poor
Priority Designation Condition Ownership Summary  Building/Address Priority Designation Condition Ownership	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church, C (C) Grade II, Conservation Area Poor Religious organisation
Priority Designation Condition Ownership Summary  Building/Address Priority Designation Condition	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church, C (C) Grade II, Conservation Area Poor Religious organisation Brick and flint. Collapsed section on south side, including entire
Priority Designation Condition Ownership Summary  Building/Address Priority Designation Condition Ownership	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church, C (C) Grade II, Conservation Area Poor Religious organisation Brick and flint. Collapsed section on south side, including entire brick pier and gate. Some urgent repairs carried out September
Priority Designation Condition Ownership Summary  Building/Address Priority Designation Condition Ownership	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church, C (C) Grade II, Conservation Area Poor Religious organisation Brick and flint. Collapsed section on south side, including entire brick pier and gate. Some urgent repairs carried out September 2010 to replace missing flints and fill holes, to ensure short term
Priority Designation Condition Ownership Summary  Building/Address Priority Designation Condition Ownership	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church, C (C) Grade II, Conservation Area Poor Religious organisation Brick and flint. Collapsed section on south side, including entire brick pier and gate. Some urgent repairs carried out September 2010 to replace missing flints and fill holes, to ensure short term preservation. Further repairs awaiting resolution of the future of
Priority Designation Condition Ownership Summary  Building/Address Priority Designation Condition Ownership	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church, C (C) Grade II, Conservation Area Poor Religious organisation Brick and flint. Collapsed section on south side, including entire brick pier and gate. Some urgent repairs carried out September 2010 to replace missing flints and fill holes, to ensure short term
Priority Designation Condition Ownership Summary  Building/Address Priority Designation Condition Ownership	Adelaide Crescent , Retaining walls to south side of gardens, C (C) Grade II, Conservation Area Poor Local authority Retaining wall to public gardens c1830, designed by Decimus Burton. Render over brick with vermiculated rustication. The rendering is gradually becoming detached from the brickwork and the detailing lost. Funding options to secure repairs are being investigated.  Blatchington Road, Walls to churchyard of Holy Trinity Church, C (C) Grade II, Conservation Area Poor Religious organisation Brick and flint. Collapsed section on south side, including entire brick pier and gate. Some urgent repairs carried out September 2010 to replace missing flints and fill holes, to ensure short term preservation. Further repairs awaiting resolution of the future of

Duilding/Addrsss	Clausagter Place 10.14 The Asterio Theatre
Building/Address	Gloucester Place, 10-14, The Astoria Theatre
Priority	D (D)
Designation	Grade II, Conservation Area
Condition	Poor, vacant
Ownership	Private
Summary	Former cinema, 1933. Vacant since 1997. Ground floor
	frontage redecorated and secured but building not fully weather
	tight. Significant structural repairs needed and no viable use
	found. The council has granted listed building consent for the
	demolition of the building and planning permission for
	redevelopment but no works have commenced. Revised
	applications have recently been submitted.
Duilding/Address	Hangleton Long Bonfield Born
Building/Address	Hangleton Lane, Benfield Barn
Priority	C (C)
Designation Condition	Grade II, Conservation Area  Poor, partially occupied
	, i , i , i , i , i , i , i , i , i , i
Ownership	Company
Summary	Barn, probably 18 <sup>th</sup> century. Coursed flint. Lease has changed hands regularly. No maintenance plan. Barn itself in use as
	tractor store and in fair condition but three historic outbuildings
	have collapsed and a fourth is in poor condition.
Building/Address	Preston Drove, Wellhouse to Preston Manor
Priority	A (A)
Designation	Grade II, Conservation Area
Condition	Very bad
Ownership	Local authority
Summary	Circa 1735. Ruinous. Collapsed flint walls, no roof, invaded by
Summary	extensive plant and tree growth. Cast iron winding gear
	survives largely intact. An appropriate approach for the
	stabilisation of this building and the identification of funding for
	such works are being actively explored.
	Cash works are being delivery explored.
Building/Address	Preston Street, 67
Priority	C (C)
Designation	Grade II, Conservation Area
Condition	Poor, vacant
Ownership	Private
Summary	Included in the listing for 22-25 Regency Square. Town house
- Janimary	dating from c1818. Ground floor to Preston Street with later
	shop front. Upper floors last in use as offices. Structural
	problems and some water ingress. Planning Permission and
	Listed Building Consent for conversion to an HMO were refused
	in 2012. A revised application has been submitted and is under
	consideration.
Building/Address	Russell Square, 43
Priority	C (C)

Designation	Grade II
Condition	Poor, vacant
Ownership	Private.
Summary	Terraced house c1820, probably by Amon Wilds. Subject to past squatting and resulting damage. Now in new ownership. Planning Permission was refused in 2013 to convert the building to an HMO and basement flat with external and internal alterations, though Listed Building Consent was granted. A certificate of lawfulness application has been submitted for conversion to a small HMO and is under consideration
Puilding/Addross	Ship Street, 51, Post Office
Building/Address	C (C)
Priority	
Designation	Grade II, Conservation Area
Condition	Poor, vacant.
Ownership Summary	Company  Main building of 1025 incorporating parts of an earlier building
Summary	Main building of 1925, incorporating parts of an earlier building of c1895, with annexe to the south of 1849. Main building no longer in use and being marketed. Following the eviction of squatters a comprehensive programme of repair works has now commenced on the building. Planning consents have been granted for the conversion of the ground floor frontage into restaurant use and conversion works are expected to commence once the external repairs have been carried out. A further planning application for residential use for the upper floors is expected.
Building/Address	Stanford Avenue, St Augustine's Church
Priority	D (D)
	\ /
Designation	Grade II, Conservation Area
Condition	Poor, partially occupied
Ownership	Religious organisation
Summary	Nave of 1896, chancel of 1914 by GES Streatfield. Red brick. The church is in partial use but the attached hall is vacant. Neither are weathertight. A planning application to convert the church to community use and the hall to residential was approved in October 2012 subject to a s106 agreement and discussions on the agreement are ongoing. Listed Building Consent was granted for the necessary alterations and was linked by condition to a schedule of repair works. In 2013 action was taken to require the removal of ivy and other plant growth from the walls of the church and to board over the entrance to the church hall.
Building/Address	Stone Street, 13A and 14
Priority	C (C)
Designation	Grade II, Conservation Area
Condition	Poor, vacant
Ownership	Private
CMIICIGIIIP	i iivato

	I — th
Summary	Early 19 <sup>th</sup> century stables and coach house buildings. Listed in
	September 2012. Planning applications have been submitted
	for the retention and restoration of these buildings and the
	redevelopment of adjoining land and buildings.
Building/Address	The Square, 19 and 20
Priority	A (C)
Designation	Grade II, Conservation Area
Condition	Poor, vacant
Ownership	Private.
Summary	Later 18 <sup>th</sup> century terraced outbuildings in flint with brick
	dressings. Long vacant and in disrepair. Planning applications
	have been submitted for the retention and repair of these
	buildings, with a new extension, to form a single dwellinghouse.
Listed Buildings co	onsidered Vulnerable
	Grade I
Building/Address	R/O Brunswick Square, 14 (38 Brunswick Street East)
Priority	F (F)
Designation	Grade I, Conservation Area
Condition	Fair, partially occupied
Ownership	Private
Summary	Terraced house 1825-27 in multiple occupancy. The rear part,
	known as 38 Brunswick Street East, is at risk. Consent granted
	for conversion to a self-contained dwelling in 2005. Conversion
	and repair works largely carried out and ground floor occupied,
	but works to basement are still unfinished.
	Grade II*
Building/Address	Old Steine, 54, Marlborough House
Priority	E (E)
Designation	Grade II*, Conservation Area
Condition	Fair, vacant
Ownership	Private
Summary	Original house 1765 but remodeled 1786 by Robert Adam.
_	Most recently used as offices but vacant for a number of years.
	Now fully weather tight and secure but full repair works not
	completed and no solution in place for its reuse and full
	restoration.
	Grade II
Building/Address	Blatchington Road, Holy Trinity Church
Priority	E (E)
Designation	Grade II, Conservation Area
Condition	Fair, vacant
Ownership	Religious organisation
Summary	1863-64, tower 1866, red brick with Bath stone dressings.
	Declared redundant under the Pastoral Measure 1983. Long
	term future uncertain. Discussions on possible reuse ongoing.

	Action taken during 2013 to require removal of extensive plant
	growth from exterior of building.
Building/Address	St George's Place, 2
Priority	F (D)
Designation	Grade II, Conservation Area
Condition	Fair, vacant
Ownership	Company
Summary	Terraced house of c1825. Probably by Wilds and Busby. Long-term vacant. Urgent works carried out by default under S54 of the Planning (Listed Buildings & Conservation Areas) Act. Planning permission and listed building consent granted in 2011 for restoration and conversion to flats and works to implement this are in progress.
D '11' (A 1 1	
Building/Address	Sussex Street, Tower and walls in Tarner Recreation Ground
Priority	E (E)
Designation	Grade II, Conservation Area
Condition	Fair
Ownership	Local Authority
Summary	Lookout tower in public park, 1832. Knapped flint. No public access to tower. The tower has been cleaned of graffiti and made secure but a need for specific repairs has been identified following full survey. An initial bid for HLF funding was unsuccessful but The Friends of Tarner Park intend to make a fresh bid once listed building consent has been secured for new handrails and the reinstatement of a weathervane.

## **Footnote**

Priority for action follows the criteria set out by English Heritage, which are based on how fast a building is likely to deteriorate without intervention, and it may not necessarily be those buildings in the worst condition that are afforded highest priority.

Priority for action is graded as follows:

- A Immediate risk of further rapid deterioration or loss of fabric; no solution agreed
- B Immediate risk of further rapid deterioration or loss of fabric; solution agreed but not yet implemented
- C Slow decay; no solution agreed
- **D** Slow decay; solution agreed but not yet implemented
- E Under repair or in fair to good repair, but no user identified; or under threat of vacancy with no obvious new user (for buildings capable of beneficial use)
- F Repair scheme in progress and (where applicable) end use or user identified; functionally redundant buildings with new use agreed but not yet implemented.