| School | Bid | Priority | Completing 2021/22 | Carry forward to 2022/23 |
|--|--|--|--|--|
| Asbestos Coombe Road | Replace external canony including ashestos removal | D2 | | £12.000.00 |
| Socialist Road | Replace external canopy including asbestos removal | Sub total | £0 | £12,000 |
| Seneral Building works | | | | |
| Balfour Primary | Re-pointing works at Balfour | D2 | £15,000.00 | |
| Blatchington Mill | Repointing and wall ties to Block 2 and 6th form | D3 | £20,000.00 | |
| Carlton Hill Coombe Road | Replace curtain walling phase 2 south elevations Replace lintels to the staff room | D2 D1 | £60,000.00 | £30,000.00 |
| Downs View Life Skills | Recover plain clay tiles above offices, domestic science room | D2 | £60,000.00 | 200,000.00 |
| | and Old Coach-house | | | |
| Downs View Life Skills Fairlight Primary | Structural glazing Replace curtain walling to gym Replace wall ties and re-pointing – inner elevations | D2 D2 | £80,000.00 £25,000.00 | |
| langleton Primary | Repointing/wall tie replacement (south elevation) | D2 | £8,000.00 | |
| Hove Park Lower | Re-pointing and wall tie replacement to south and west elevations | D2 | | £25,000.00 |
| love Park Upper | Re-pointing & wall ties to hall (VI Form block south elevation) | D2 | £45,000.00 | |
| love Park Upper | Recover metal and 2no corridor flat roofs above rooms | D2 | £143,000.00 | |
| eanne Saunders | Major renewal of rainwater goods, including soil pipes, lintels, | D2 | £50,000.00 | |
| onghill High | 2 no large structural windows and re-pointing Replace structural glazing to staircase A Block south | D1 | £90,000.00 | |
| onghill High | Replace structural glazing to staircase A Block north | D2 | £90,000.00 | |
| onghill High | Replace curtain walling to block 4 ground, first and second | D2 | £100,000.00 | |
| loulsecoomb Primary | floors Finish the boxing works | D2 | £30,000.00 | |
| ortslade Sports C. | Cladding defects | D2 D2 | £10,000.00 | |
| ueens Park | Repointing and masonry works to the South elevation. | D2 | £25,000.00 | |
| ueens Park | Remedial works to boundary walls to premises managers | D2 | £9,000.00 | |
| toyal Spa | house Rendering to boundary wall | D2 | £7,000.00 | |
| tanford Infant | Refurbish caretaker's kitchen | D2 D2 | £10,000.00 | |
| Surrenden Pool | Refurbishment works to girls and boys changing rooms | D2 | £150,000.00 | |
| Vest Hove Infant (Connaught | Re pointing front and rear elevations | D2 | | £15,000.00 |
| (d) | Replace fire egress ramp/stair to library (50/50 split with Corp | D1 | £30,000.00 | |
| Vestdene Primary | PMB) | | | |
| Voodingdean Primary | Re-pointing/wall ties (courtyard and front entrance) | D2 Sub total | £10,000.00 £1,067,000.00 | £70,000.00 |
| | | Sub total | 21,007,000.00 | 270,000.00 |
| oofing works | | | | |
| latchington Mill | Recover flat roof to former sixth form block Flat roof replacement above Reception, corridor, Activity Area | D2 | £90,000.00 | |
| runswick Primary | and Hall Two | D1 | £70,000.00 | |
| owns View Special | Replace flat roof covering to lift plant room | D2 | £30,000.00 | |
| lill Park Lower | Replacement flat roof covering (Playroom, Staff Room, Music | D1 | £48,000.00 | |
| 10.11 | Therapy, Medical room) Replacement flat roof covering– dining room, classroom, | D 0 | 050 000 00 | |
| Homewood College | toilets, store and 1-1 room (ground floor block 2) | D2 | £50,000.00 | |
| onghill High | Recover flat roofs above changing and drama rooms – phase 3 | D1 | £172,000.00 | |
| Mile Oak | Flat roof on Two storey block | D1 | £99,000.00 | |
| Saltdean | Flat roof Block D1 (gas pipe) | D1 | £115,000.00 | |
| Vestdene Primary | Recover pitched felt roof above library area and classroom | D1 Sub total | £52,000.00 | 22.22 |
| | | Sub total | £726,000.00 | £0.00 |
| lechanical works | | | | |
| Benfield Primary | Replace heating pipework below floor | D2 | £60,000.00 | £180,000.00 |
| Coombe Road | Replace Boiler Control/Panel in -1/003 | D2 | £8,000.00 | |
| airlight Primary | | | , | |
| Hertford Infant | Old Heating distribution, (including ceilings and lighting in Gf and Ff) | D2 | Fees | £350,000.00 |
| | and Ff) Replace heating system | D2 | Fees £25,000.00 | £350,000.00 £238,000.00 |
| love Park Lower | and Ff) Replace heating system Replace fan coil units | | Fees | |
| | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos | D2 | Fees £25,000.00 | |
| Hove Park Lower Mile Oak St Luke's | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and | D2 D2 D2 | Fees £25,000.00 £87,000.00 £20,000.00 | £238,000.00 |
| /lile Oak St Luke's | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. | D2 D2 D2 | Fees £25,000.00 £87,000.00 £20,000.00 Fees | |
| /lile Oak St Luke's | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and | D2 D2 D2 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 | £238,000.00 £950,000.00 |
| file Oak St Luke's Stanford Infant | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. | D2 D2 D2 D2 D2 | Fees £25,000.00 £87,000.00 £20,000.00 Fees | £238,000.00 |
| file Oak St Luke's Stanford Infant Electrical works | and Ff) Replace heating system Replace fan coil units Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services | D2 D2 D2 D2 D2 Sub total | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 | £238,000.00 £950,000.00 |
| file Oak St Luke's Stanford Infant Slectrical works | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. | D2 D2 D2 D2 D2 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 | £238,000.00 £950,000.00 |
| file Oak St Luke's Stanford Infant Electrical works Carlton Hill | and Ff) Replace heating system Replace fan coil units Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical | D2 D2 D2 D2 D2 Sub total | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 | £238,000.00 £950,000.00 |
| tile Oak It Luke's Itanford Infant Itectrical works Itariton Hill Items View Special | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical distribution boards | D2 D2 D2 D2 D2 Sub total | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 | £238,000.00 £950,000.00 |
| tile Oak It Luke's Itanford Infant Ilectrical works Icarlton Hill Jowns View Special Ilm Grove Primary | and Ff) Replace heating system Replace fan coil units Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical | D2 D2 D2 D2 Sub total | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 | £238,000.00 £950,000.00 |
| tile Oak t Luke's tanford Infant lectrical works arlton Hill towns View Special Im Grove Primary airlight Primary | and Ff) Replace heating system Replace fan coil units Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace Snr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services | D2 D2 D2 D2 D2 Sub total | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 | £238,000.00 £950,000.00 £1,718,000.00 |
| tile Oak It Luke's Itanford Infant Ilectrical works Ilectrical works Infant Ill Infa | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 | D2 D2 D2 D2 D2 Sub total | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £55,000.00 | £238,000.00 £950,000.00 £1,718,000.00 |
| tile Oak It Luke's Itanford Infant Ilectrical works Ilectrical | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms | D2 D2 D2 D2 Sub total | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £50,000.00 £140,000.00 | £238,000.00 £950,000.00 £1,718,000.00 |
| tile Oak It Luke's Itanford Infant Ilectrical works Ilectrical | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replace hall ceiling, power and lighting Replacement of electrical services to sports hall, including | D2 D2 D2 D2 Sub total | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £140,000.00 £140,000.00 £140,000.00 | £238,000.00 £950,000.00 £1,718,000.00 |
| file Oak St Luke's Stanford Infant Stectrical works Carlton Hill Downs View Special Eilm Grove Primary Fairlight Primary Hove Park Lower Hove Park Lower Hove Park Upper Hove Park Upper | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replace hall ceiling, power and lighting Replacement of electrical services to sports hall, including lighting & emergency lighting. | D2 D2 D2 D2 Sub total D3 D2 D3 D2 D3 D2 D2 D2 D2 D2 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £50,000.00 £140,000.00 £140,000.00 £110,000.00 | £238,000.00 £950,000.00 £1,718,000.00 |
| file Oak St Luke's Stanford Infant Stectrical works Carlton Hill Downs View Special Eilm Grove Primary Fairlight Primary Hove Park Lower Hove Park Lower Hove Park Upper Hove Park Upper | and Ff) Replace heating system Replace fan coil units Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replace hall ceiling, power and lighting Replacement of electrical services to sports hall, including lighting & emergency lighting. Replacement of electrical services including external security lighting | D2 D2 D2 D2 Sub total | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £140,000.00 £140,000.00 £140,000.00 | £238,000.00 £950,000.00 £1,718,000.00 |
| | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace Snr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replace hall ceiling, power and lighting Replacement of electrical services to sports hall, including lighting & emergency lighting. Replacement of electrical services including external security lighting. Replacement of electrical services including external security lighting. Replace ground floor ceilings to corridor and classrooms, | D2 D2 D2 D2 Sub total D3 D2 D3 D2 D3 D2 D2 D2 D2 D2 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £50,000.00 £140,000.00 £140,000.00 £110,000.00 | £238,000.00 £950,000.00 £1,718,000.00 |
| Alile Oak St Luke's Stanford Infant Electrical works Carlton Hill Downs View Special Elm Grove Primary Fairlight Primary Hove Park Lower Hove Park Lower Hove Park Upper Lynchet Close PRU Lynchet Close PRU Hove Park Upper | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace Snr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replace hall ceiling, power and lighting Replacement of electrical services to sports hall, including lighting & emergency lighting. Replacement of electrical services including external security lighting Replace ground floor ceilings to corridor and classrooms, power and lighting | D2 D2 D2 D2 Sub total D3 D2 D3 D2 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £25,000.00 £140,000.00 £140,000.00 £10,000.00 | £238,000.00 £950,000.00 £1,718,000.00 £35,000.00 |
| Alile Oak St Luke's Stanford Infant Electrical works Carlton Hill Downs View Special Elm Grove Primary Fairlight Primary Hove Park Lower Hove Park Lower Hove Park Upper Lynchet Close PRU Lynchet Close PRU Hove Park Upper | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replace hall ceiling, power and lighting Replacement of electrical services to sports hall, including lighting & emergency lighting. Replacement of electrical services including external security lighting Replacement of electrical services including external security lighting Replacement floor ceilings to corridor and classrooms, power and lighting Replacement power, lighting, asbestos removal and new ceilings (ground floor) | D2 D2 D2 D2 Sub total D3 D2 D3 D2 D3 D2 D2 D2 D3 D2 D2 D3 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £25,000.00 £140,000.00 £140,000.00 £50,000.00 £50,000.00 £50,000.00 | £238,000.00 £950,000.00 £1,718,000.00 |
| Afile Oak St Luke's Stanford Infant Electrical works Carlton Hill Downs View Special Elm Grove Primary Fairlight Primary Hove Park Lower Hove Park Lower Hove Park Upper Hynchet Close PRU Hynchet Close PRU Hove Park Upper | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replace hall ceiling, power and lighting Replacement of electrical services to sports hall, including lighting & emergency lighting. Replacement of electrical services including external security lighting Replace ground floor ceilings to corridor and classrooms, power and lighting Replacement power, lighting, asbestos removal and new | D2 D2 D2 D2 Sub total D3 D2 D3 D2 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £250,000.00 £140,000.00 £140,000.00 £10,000.00 £50,000.00 £50,000.00 | £238,000.00 £950,000.00 £1,718,000.00 £35,000.00 |
| Alile Oak St Luke's Stanford Infant Electrical works Carlton Hill Downs View Special Elm Grove Primary Fairlight Primary Hove Park Lower Hove Park Lower Hove Park Upper Lynchet Close PRU Lynchet Close PRU Hove Park Upper | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace 5nr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replace hall ceiling, power and lighting Replacement of electrical services to sports hall, including lighting & emergency lighting. Replacement of electrical services including external security lighting Replacement of electrical services including external security lighting Replacement floor ceilings to corridor and classrooms, power and lighting Replacement power, lighting, asbestos removal and new ceilings (ground floor) | D2 D2 D2 D2 Sub total D3 D2 D3 D2 D3 D2 D2 D2 D3 D2 D2 D3 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £25,000.00 £140,000.00 £140,000.00 £50,000.00 £50,000.00 £50,000.00 | £238,000.00 £950,000.00 £1,718,000.00 |
| Alile Oak St Luke's Stanford Infant Electrical works Carlton Hill Downs View Special Elm Grove Primary Fairlight Primary Hove Park Lower Hove Park Lower Hove Park Upper Lynchet Close PRU Lynchet Close PRU Hove Park Upper Aliddle Street Alide Oak | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace Snr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replace hall ceiling, power and lighting Replacement of electrical services to sports hall, including lighting & emergency lighting. Replacement of electrical services including external security lighting Replace ground floor ceilings to corridor and classrooms, power and lighting Replacement power, lighting, asbestos removal and new ceilings (ground floor) Replace ceiling to gym, power and lighting | D2 D2 D2 D3 D2 D2 D3 D2 D3 D2 D2 D3 D2 D3 D2 D3 D2 D3 D2 D3 D2 D3 D4 D5 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £250,000.00 £140,000.00 £140,000.00 £10,000.00 £50,000.00 £50,000.00 | £238,000.00 £950,000.00 £1,718,000.00 £35,000.00 £100,000.00 |
| dile Oak St Luke's Stanford Infant Stectrical works Carlton Hill Downs View Special Stilm Grove Primary airlight Primary dove Park Lower dove Park Lower dove Park Upper synchet Close PRU synchet Close PRU dove Park Upper diddle Street dile Oak Stillets Carden Primary | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace Snr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replacement of electrical services to sports hall, including lighting & emergency lighting. Replacement of electrical services including external security lighting Replacement of electrical services including external security lighting Replace ground floor ceilings to corridor and classrooms, power and lighting Replacement power, lighting, asbestos removal and new ceilings (ground floor) Replace ceiling to gym, power and lighting | D2 D2 D2 D2 Sub total D3 D2 D3 D2 D2 D2 D2 D2 D2 D2 D2 D3 D2 D2 D3 D2 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £250,000.00 £140,000.00 £140,000.00 £10,000.00 £50,000.00 £50,000.00 | £238,000.00 £950,000.00 £1,718,000.00 £35,000.00 £135,000.00 |
| Alile Oak St Luke's Stanford Infant Electrical works Carlton Hill Downs View Special Elm Grove Primary Fairlight Primary Hove Park Lower Hove Park Lower Hove Park Upper Lynchet Close PRU Lynchet Close PRU Hove Park Upper | and Ff) Replace heating system Replace fan coil units Replace boiler to 1990's extension and potential asbestos removal Change old heating, mains conversion, hot & cold water and lighting. Replace H&C Services 4 Way MCCB Panel Board in Switch Panel, future replacement with a 6 Way Panel Board Replace Snr 3 phase and 6nr single phase electrical distribution boards Replace old inefficient lighting Rewire and replace lighting, rewire to first floor classrooms. Partial replacement of electrical services Replace ground floor ceilings, power and lighting 2 technology 1 food-tech rooms Replace hall ceiling, power and lighting Replacement of electrical services to sports hall, including lighting & emergency lighting. Replacement of electrical services including external security lighting Replace ground floor ceilings to corridor and classrooms, power and lighting Replacement power, lighting, asbestos removal and new ceilings (ground floor) Replace ceiling to gym, power and lighting | D2 D2 D2 D3 D2 D2 D3 D2 D3 D2 D2 D3 D2 D3 D2 D3 D2 D3 D2 D3 D2 D3 D4 D5 | Fees £25,000.00 £87,000.00 £20,000.00 Fees £80,000.00 £280,000.00 £250,000.00 £140,000.00 £140,000.00 £10,000.00 £50,000.00 £50,000.00 | £238,000.00 £950,000.00 £1,718,000.00 £35,000.00 £100,000.00 |

| | | Total (inc. fees) | £3,952,300.00 | £2,370,500.00 |
|---|--|----------------------------------|-------------------------------------|----------------------------------|
| | | TOTAL (Excl. fees) Fees (@10% | £3,593,000.00 £359,300.00 | £2,155,000.00 £215,500.00 |
| | | Sub total | £219,000.00 | 00.03 |
| Woodingdean Primary | Resurface West playground | D2 | £12,000.00 | |
| Rudyard Kipling | Resurface playground 59P and 1T as shown on grounds plan) | D3 | £45,000.00 | |
| Rudyard Kipling | Resurface playgrounds and paths 28P, 23T & including path leading to Downs Valley Road | D2 | £30,000.00 | |
| Hove Park Upper | Resurface playground and car park | D2 | £50,000.00 | |
| Coldean Primary | Resurface infant site playground and outside classroom paved areas | D2 | £35,000.00 | |
| Carden Primary | Resurface playground | D2 | £12,000.00 | |
| Resurfacing works Balfour Primary | Re-surfacing to EYFS and Year 2 paved areas | D2 | £35,000.00 | |
| , | | Sub total | £700,000 | £220,000 |
| Woodingdean Primary | Refurbish YR3 toilets | D3 | £80,000.00 | |
| Saltdean | Refurbish toilets – Year 1 boys and girls (North Block) | D3 D2 | £90,000.00 | £55,000.00 |
| Moulsecoomb Primary Moulsecoomb Primary | Toilet Refurbishment - First Floor Boys Toilet Refurbishment - First Floor Girls | D3 D3 | | £55,000.00 £55,000.00 |
| Mile Oak | Refurbish toilets 0/078 & 0/080 | D3 | £80,000.00 | |
| Longhill High | Room B006 (Block 3) Boys toilet refurbishment | D1 | £50,000.00 | |
| Longhill High | Room A103 (Block 1) Male staff toilet refurbishment) | D1 | £50,000.00 | |
| Hove Park Upper | Toilet refurbishment (LRC – male and female) Library wing Girls Toilets | D2 | £100,000.00 £60,000.00 | |