

APPENDIX 2

Property	Description of works	Budget estimate
General works		£248,000
Coombe Road School	Repoint West facing side of clock tower	
Balfour Primary School (Junior)	Replace timber cladding to West elevation	
Blatchington Mill School	Replacement lintels and wall ties to courtyard	
Brackenbury Primary School	Refurbish girls toilet by Head's office	
Downs View School	Replace ramp to mobile in Ash Cottage garden	
Elm Grove Primary School	Refurbish lower ground floor toilets	
Fairlight Primary School	Toilet refurbishment boys & girls phase 1	
Jeanne Saunders Centre	Investigate and remedy damp to chimneys	
Jeanne Saunders Centre	Refurbish basement toilets	
Jeanne Saunders Centre	Remedial works to corroded steel beams	
Longhill School	Repair spalling concrete to Block A & Block 3	
West Blatchington Primary School	Replace wall ties to front elevation (infant side)	
West Hove Junior School	Repairs to chimney stacks phase 2	
West Hove Junior School	Lintel repairs/replacement	
Woodingdean Community Centre	Refurbish female toilets	
Woodingdean Community Centre	External redecoration & timber repairs	
Flat Roofing Works		£766,800
Blatchington Mill School	Replace roof covering above rooms 153-160	
Carden Primary School	Flat roof replacement above hall and corridor	
Coldean Primary School	Recover flat roof above rooms 13-25	
Hangleton Junior School	Replace flat roof coverings above hall, dining hall & Junior corridor	
Hove Park School	Replace corridor roofs (upper school)	
Portslade Sports Centre	Replace single storey flat roofs (West elevation)	
Woodingdean Primary School	Recover roof above classrooms 10,17&21 & YR6 corridor. Phase 2	
Downs Infant School	Recover flat roofs above main reception and offices	
Stanford Infants School	Replace flat roof	
Middle Street Primary School	Replace flat roof above hall	
Stanford Junior School	Flat roof replacement, over haul pitched roof and masonry repairs	
West Hove Junior School	Flat roof repairs to corridor flat roofs	
West Hove Junior School	Flat roof repairs (high level)	
Pitched Roofing Works		£285,000
Balfour Primary School (Junior)	Replace tiled roof above library and classrooms	
Downs Junior School	Replace pitched roofs	
Moulsecoomb Primary School	Replace pitched roof covering	
Caretaker's House		
Patcham Junior School	Recover pitched roof above class 7	
St Georges House PRU	Recover pitched roofs phase 2	
1-3 Vardean Cottages	Replacement pitched roofs	
Mechanical works		£857,000
Woodingdean Primary School	Replace boilers	
Carden Primary School	Replacement Heating phase 2	
Coldean Primary School	Replacement Heating phase 2	
Hangleton Infant & Junior Schools	Replacement Heating phase 3	
Patcham House School	Replace fan coil units	
Hertford Infant School	Replacement boilers	
Mile Oak Primary School	Replace water heaters	
Mile Oak Primary School	Replace boiler plant	
Resurfacing works		£90,000
Carden Primary School	Drainage improvement works outside KS1 & KS2	
Downs View School	Tarmac footpath between play areas	
Moulsecoomb Primary School	Resurface L-shaped playground & replace paving by steps	
Stanford Infant School	Resurface top playground/ repairs to steps	
Tilbury House	Resurfacing works leading to main entrance	
Longhill School	Resurface middle tennis court	
Stanford Infant School	Resurface car park and path	
TOTAL		£2,246,800