

North Laine and station area



1



1



2




2




3



4




5



5



6



7



7



8



12




10



11



11



12



13



14




15

2.2 Detailed sign audits

A detailed audit of the existing signing was carried out in the area where the first signs will be installed. A record was made of where information and signs are currently located, where pedestrians need wayfinding information, if there might be a problem with any of the proposed locations and the level of clutter removal.

A thorough evaluation of each proposed sign and possible clutter removal item location will be undertaken as part of the implementation phase.



15

